


**SR 92 and I-90 Intersection Improvements and Regionwide Roadside Safety Project
RFP Questions and Answers # 2 - January 31, 2013**

<div> <div>KEY:</div> <div>  New/Updated </div> </div>				
Question	RFP Reference	Question	Date Received	Response
1	2.18.1; page 2.18-1, lines 14-15	Confirm existing strand count for the fiber optic cable which will be re-routed and spliced in a new cable vault.	1/7/2013	See Addendum 2 which includes the ITS plan sheets from I-90 Eastgate Transit Access 142nd Place SE.
2	2.18.1; page 2.18-1, lines 14-15	Provide an existing splice detail for the fiber optic cable which will be re-routed and spliced in a new cable vault.	1/7/2013	See Addendum 2 which includes the ITS plan sheets from I-90 Eastgate Transit Access 142nd Place SE.
3	2.18.1; page 2.18-1, lines 14-15	Will the new cable vault replace the existing pull box located just east of the cabinet pad shown on sheet IT15 of the I-90 Eastgate Transit Access 142nd Place SE contract, or will the new cable vault be installed in addition to the existing pull box for the fiber optic cable which will be re-routed and spliced in a new cable vault?	1/7/2013	See Appendix T29 and Addendum #4
4	2.18.1; page 2.18-1, lines 14-15	What specific modifications are required inside the existing camera cabinet?	1/7/2013	See Appendix T29 and Section 8-20 of the Special Provisions. Additional information will be added by Addendum 4.
5	2.18.1; page 2.18-1, lines 14-15	Please provide all ITS-related plan sheets from the I-90 Eastgate Transit Access 142nd Place SE contract.	1/7/2013	See Addendum 2 which includes the ITS plan sheets from I-90 Eastgate Transit Access 142nd Place SE.
6	2.18.1; page 2.18-1, lines 19-20	Please provide a detailed description of the modifications required inside the existing ramp meter cabinet.	1/7/2013	See Appendix T29 and Addendum #4
7	2.18.1; page 2.18-1, lines 21-23	Please confirm that the existing ramp meter queue loops will require replacement.	1/7/2013	See Appendix T29 and Addendum #4
8	Appendix O2d	Does using a cross slope other than -2% in the roundabout circulating lane require a deviation?	1/18/2013	WSDOT is currently preparing an update to the Project Analysis for Location D to include the proposed cross slope.
9	Appendix H4	Please confirm this project is to meet the 170% detention requirement as stated in Appendix H4 Hydraulic Report for Existing Pond, in addition to the project requirement for detention of new impervious surface.	1/28/2013	See Addendum 4 for clarification of requirements.
10	1-07.2	Please provide the Contact Documents that identify those parts of the Project that require Work related to State Department of Revenue Rule 170 and 171.	1/28/2013	See Appendices R1a, R1b, and R1d. Rule 171 applies to Locations A and B. Rule 170 applies to Location C and D.
11	Location C	For location C, please provide the beginning and end mile post limits of the redirection landforms that need protection with placement of guardrail.	1/28/2013	See Addendum 4 for updated Appendices M1c and O1c.